

## ELECTRIC HEATED PLATES

17510000	1200x400mm ELECTRIC HEATED PLATE
17610000	1200x500mm ELECTRIC HEATED PLATE
17710000	1200x600mm ELECTRIC HEATED PLATE
1450600002	600x400mm 110V/70W ELECTRIC HEATED PLATE
17500006	1200 SUPPORT PLATE (KIT 4 PIECES)


This models of big size plates allow heating areas to create microclimates of great comfort in farrowing, weaning and wean to finish. Electric system.



1200x600

1200x500


1200x400



The special design of the easy to install "out-dirt" panel support. It comes as a four-part kit.

- Allows individual switching off of the plates.
- Low power consumption.
- Very comfortable for the piglets.
- Very resistant, even to the sow step.
- Without corners for an easy cleaning.
- Comfortable with anti-slipping surface.

TECHNICAL DATA	60x40	120x40	120x50	120x60
Power, W	70	120	150	180
Voltage, V	110	230		
Length of the connection cable, m	4			



600x400

## Heated Plates Complements

E0000235	HF20C/230V CONTROLLER WITH SWITCHES
E0000294	HF20S/110V CONTROLLER
E0000236	HF20S/230V CONTROLLER

The controllers set voltage supplied to the plates: a higher voltage, higher temperature.



- HF20S - Controller for farrowing and weaning.
- HF20C - Regulator with switches, which allows up to 20 individuals farrowing places.

TECHNICAL DATA	HF20S	HF20C
Maximum power, W	3000	3000
Maximum power x switch	-	150